



#122

UNITED STATES DEPARTMENT OF COMMERCE
Patent and Trademark Office
ASSISTANT SECRETARY OF COMMERCE AND
COMMISSIONER OF PATENTS AND TRADEMARKS
Washington, D.C. 20231

Oct. 9, 2003

Patent No.: 6,316,806B1

Issue: November 13, 2001

Inventors: Brian Sze-Ki Mo

Title: TRENCH TRANISTOR WITH A SELF-ALIGNED SOURCE

Re: Request for Certificate of Correction

Consideration has been given your request for the issuance of a certificate of correction for the above-identified patent.

The patent does not read as shown in the certificate of correction, because, as shown in the specification (col. 6, line 62, through col. 7, line 5) and in Figs. 6A and 6C, the relevant rotation angle is measured with respect to the direction of the implantation: and the change of the rotation angle from the original 90 degrees to 180 degree would make the second implantation unworkable as it would cause the back of substrate (600) to face the implantation source (604).

In view of the foregoing, your request is hereby denied.

Further consideration will be given upon receipt of a Request for Reconsideration, which should be directed to Decisions and Certificate of Correction Branch. Requests for Reconsideration should be accompanied by additional support (e.g. copy of amendments, post card receipts. PTOL 1449 or 892, etc.), containing requested data or changes) and/or brief statements of facts, as requested.

M. Talley

For Cecelia B. Newman, Supervisor
Decisions and Certificate
Of Correction Branch
(703) 305-8908 or (703) 305-8228

Babak S. Sani
Townsend & Townsend and Crew
Two Embarcadero Center 8th FL.
San Francisco, CA 94111-3834

CBN/Mt